

RTI page	fleet number	brigade	area	region	date lodged	elec	immobile	body	truck manufacturer	pump	HP	reel mount	build date	mileage	pump hours	description	
1	r1885		Bundaberg	Central	7.10.25			y				01.07.23	1500			air con belt broken, wrapped around alternator	
2	r18833		Bundaberg	Central	15.09.25	y	y					01.05.25	927			17 240v input - magnet has fallen out of plastic wrap + 240v active light not functioning	
3	r18833		Bundaberg	Central	15.09.25	y				y		01.05.25	927			17 pump contol panel constantly flickers, tacho bouncing around	
4	r18833		Bundaberg	Central	15.09.25	y						01.05.25	927			17 deluge warning lights come on in truck when driving	
5	r18833		Bundaberg	Central	15.09.25	y		?				01.05.25	927			17 AMT temperature alarm. If AMT was placed in neutral alarm stopped, if in gear alarm sounded.	
6	r18833		Bundaberg	Central	15.09.25	y	y	?		y	y	01.05.25	927			17 delay on high pressure is longer than 10 seconds	
10	r18746		Fraser Coast Cooloola	Central	10.04.25	y				y	y					high pressure alternator belt failure	
10	r18841		Fraser Coast Cooloola	Central	04.07.25	y				y	y					high pressure alternator belt failure	
10	r19173		Fraser Coast Cooloola	Central	31.08.25		y			y						pump failure - PTO shaft sheered	
10	r18841		Fraser Coast Cooloola	Central	01.09.25		y			y	y					high pressure bung missing	
10	r18834		Fraser Coast Cooloola	Central	08.09.25		y			y	y					reversing camera intermittent	
14	r18746		Fraser Coast Cooloola	Central	1.09.25	y	y	?				01.03.25				AMT fault on dash. Unable to change out of first gear	
15	r18834		Fraser Coast Cooloola	Central	08.09.25			y								reversing camera not working	
16	r18841		Fraser Coast Cooloola	Central	01.11.24		y			y	y					high pressure housing is missing, pump issues water from bottom of housing	
17	r19173		Fraser Coast Cooloola	Central	31.08.25		y			y		01.11.23	3425			PTO pump makes grinding sound. Pump unable to be used	
18	r18841		Fraser Coast Cooloola	Central	04.07.25	y				y	y	01.11.24	1986	145		high pressure alternator belt failure	
19	r18746		Fraser Coast Cooloola	Central	10.04.25	y				y	y		12.24	851		high pressure pump losing pressure	
20	r18746		Fraser Coast Cooloola	Central	10.04.25	y				y	y		12.24	851		high pressure alternator belt failure	
26	r18746		Fraser Coast Cooloola	Central	17.09.25	y	y	?				01.03.25				AMT fault on dash. Unable to change out of first gear	
27	double up page 15																
28	double up page 16																
29	double up page 17																
30	double up page 18																
31	double up page 19																
32	double up page 20																
34	r18843		Gladstone	Central	18.06.25	y	y			y	y		1713			high and low pressure pump failures	
35	r18843		Gladstone	Central	18.06.25	y				y			1713			pump could not be started from rear control panel, could be started from inside cab	
36	r18843		Gladstone	Central	18.06.25			y		y						high pressure bung missing	
37	r18843		Gladstone	Central	18.06.25	y				y						broken on/off low pressure ignition switch on rear control panel	
38	r18843		Gladstone	Central	18.06.25											repeat of line 37	
40	r18739		Rockhampton	Central	21.07.25			y				14.10.24	1898			green in cabin clock light flickers with bumps in road - very distracting for driver	
41	r18739		Rockhampton	Central	21.07.25							14.10.24	1898			repeat of line 40	
42	r18830		Rockhampton	Central	30.10.25							07.07.23	800			no fault found	
43	r18739		Rockhampton	Central	20.06.24							20.06.24	2607			completed and checked by brigade	
44	r18735		Townsville	Northern	17.10.25			y					7500			PTO hydraulic fluid leak - 3 times now - no slack to allow for vehicle movement.	
45	r18735		Townsville	Northern	10.10.25	y	y			y			7222.9			elec control module failure	
46	r18735		Townsville	Northern	28.10.25			y								broken wire on dashboard	
47	r18735		Townsville	Northern	28.10.25											repeat of line 46	
58	r18741		Townsville	Northern	11.06.25	y				y	y		11.06.25			loose bolts alternator mounting	
64	r18741		Townsville	Northern	21.10.25		y			y						hose reel insecurity	
68	r18741		Townsville	Northern	20.11.25	y				y						water tank sensor goes off randomly	
70	r18741		Townsville	Northern	20.01.25	y				y	y					high pressure belt / bearings screeming	
71	r18741		Townsville	Northern	20.01.25			y								loose wiring clips next to hose reel	
73	r18741		Townsville	Northern	20.01.25		y									sharp edges on side of hose reel needs to be de-burred	
75	r18741		Townsville	Northern	20.01.25	y										deluge active light intermittent over bumps	
77	r18741		Townsville	Northern	20.01.25		y									hydrant filling blew top off water tank	
78	r18741		Townsville	Northern	06.05.25			y								auxiliary engine belt slipped	
80	r18741		Townsville	Northern	11.10.25		y			y		04.11.24	4000			LP + HP loose bolts	
81	r18749		North West Gulf	Northern	07.04.25	y										siren control does not work, high beam + park lights	
82	r18750		Mackay	Northern	27.05.25	y	y									electronic guages on pump flickering, water tank is swelling and contracting	
83	r18750		Mackay	Northern	27.05.25	y				y	y					HP runs for about 5 seconds and then stops	
84	r18750		Mackay	Northern	27.05.25	y				y	y					240v charger inpu tripping/ HP alternator belt broken	
85	r18750		Mackay	Northern	27.05.25											repeat of line 84	
86	r18750		Mackay	Northern	20.09.25	y	y			y	y	01.04.25				high pressure pump failure	
87	r18750		Mackay	Northern	13.10.25	y				y	y	01.04.25				HP bracket welds failure	
88	r18750		Mackay	Northern	20.10.25	y				y		01.04.25				water tank sensor goes off with over 1/2 tank of water	
89	r18750		Mackay	Northern	22.10.25		y				y					hose reel bolts	
90	r18750		Mackay	Northern	13.10.25		y			y	y	01.04.25				HP bracket failure	
95	r18750		Mackay	Northern	07.10.25	y				y						LP hose reel disconnected from truck	
122	r18811		Townsville	Northern	17.10.24	y				y	y					HP starts, pressurises then stops	
123	r18811		Townsville	Northern	17.10.24											repeat of line 122	
124	r18811		Townsville	Northern	17.10.24											repeat of line 122	
125	r18811		Townsville	Northern	02.04.25	y				y	y		2024			plastic plug blew out on use	
126	r18836		North West Gulf	Northern	09.09.25	y										prior to delivery RHS rear hose reel not bolted through the RHS bearing carrier, hose reel will not roll up as the chain has no tension due to not being bolted in	
128	r18837		Townsville	Northern	21.10.25								4.24	2065			hose reel bolts
134	r18838		Mackay	Northern	22.10.25		y			y		01.01.25				hose reel bolts recall	
135	r18840	</															